

COPY

Lloyd's Register of Shipping.

(UNITED WITH THE BRITISH CORPORATION REGISTER)

1331

Port YOKOHAMA

16th April 1954

This is to Certify that I have

Surveyed the Boiler and Machinery of the S.S. "KYOKO MARU" 6891 tons
gross of Tokyo, whilst in dry dock and afloat at this port on the 9th
February 1954 and subsequently on account of Docking, Annual Boiler
Survey, & examination of Propeller & sea cocks & valves with their shell
fastenings; Installation of Oil Fuel Burning Equipment; Part LMC & Repairs,
and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report stating that all
recommendations made by me in connection therewith have
been carried out to my satisfaction, and that I have
Recommended that the record of B3 4.54, & the notation "Fitted
for oil fuel 4.54, P.P. above 150°F (now); & LMC (with date)
be made in the Register Book in the case of this vessel when
the survey has been completed.

Parts now examined: —


for Part LMC:—

Main Engine, all cyls, casings, covers, pistons, rods, valves & gear, crosshead
& crankpin brasses, guides & shoes, main bearing journals & brasses (top halves
only), crank, thrust, & intermediate shafting, reversing gears, condenser
(tested) & attached pumps, etc.

Main Thrust.

Auxiliaries, Etc:— (following in their entirety):—

Both 30 KW steam driven generators
Both Independent feed Pumps
Both Ballast Pumps
Fan engine; G.S. Pump;
Both Evaporators, distiller, & evap. pump
Oil fuel system (newly installed), with both units, & transfer Pumps, etc.


Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:
while the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to
be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for
accuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of
the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other
Agents of the Society."

008789-008794/187