

LLOYD'S REGISTER OF SHIPPING

Djalan Raja Darmo No. 130, Sourabaya, Indonesia

Telegrams: Surveyor, Sourabaya

Telephone: Darmo No. 120

Sourabaya, 13th March 1959.

sn(S)

the attention of Mr. Cook.

RECEIVED

24 MAR 1959

Dear Sir,

M.S. "INSUMAR"

With reference to my cable of 10th March, regarding the m.s. "INSUMAR",

"REGARDING WITHDRAWAL OF INSUMAR FROM CLASS DJAWATAN PELAJARAN WERE NOT MANAGERS AT THAT TIME STOP THE MANAGERS PERINDO WERE UNAWARE CLASS HAD BEEN WITHDRAWN NOW REQUEST DOCKING AND MODIFIED ENGINE SURVEYS MAY I PROCEED STOP LETTER FOLLOWING".

On 10th March the Owners Representative requested that I carry out Docking, Modified Engine and Screwshaft Surveys. I explained the ship had been withdrawn from class at the Owners request, and after a time, through an interpreter and a considerable amount of perspiration I received the following information.

Djawatan Pelajaran had the ship when new, after a few months they handed it over to P.E.L.N.I., P.E.L.N.I. returned the ship to Djawatan Pelajaran in July 1954 and Djawatan Pelajaran handed over to Pelajaran Rakjat Indonesia (PERINDO) in December 1954, and since that time PERINDO have had control of the ship. The Owners are rather anxious to continue the ships class and I have commenced the Surveys, but I shall not issue any certificates until I receive instructions from you.

Yours faithfully,

B. Borkett

B. BORKETT.

008804-008811-0124

© 2021

Lloyd's Register
Foundation

