

4m.8.45.

M

29 OCT 1945

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "EMPIRE FULHAM" REPORT Fal. No. 10320

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The FALMOUTH Surveyors report this water carrier placed in dry dock, bottom coated and on account of damages, cause not stated, minor repairs effected. The Surveyors recommend set over stem and stem plating and indented side and bottom shell plating etc. (p & s) be dealt with at the first opportunity.

It is submitted the vessel is eligible to remain as classed with record of survey 9.45 subject as recommended.

9.45 Fal. subject.



© 2020

ms
17.10.45

Lloyd's Register Foundation

008831 - 008838 - 0208

Floors
Keelsons

Have Watertight Doors been examined and found
efficient ?

Transoms, Pointers & Crutches

length