

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

IFH

24th July, 1924.


Dear Sirs,

S.

With reference to the classification in this Society's Register Book of your Motor Vessel "RAPIDO", I beg to acquaint you that the Committee have had before them a letter received from the Society's Surveyor at Havana, from which it appears that no arrangements have been made by your goodselves for carrying out the Special Survey No.1, which became due in June last year, although he has communicated with you both by telephone and letter of this subject.

In the circumstances, and in view of the fact that the year of grace allowed by the Society's Rules for the completion of the Special Survey in question expired at the end of last month, the Committee regret that they have had no alternative but to give instructions for the vessel's class to be expunged from the Register Book with a red line, indicating non-compliance with the Society's Rules.

I have to add that upon the receipt of a satisfactory report from the Society's Surveyors on the completion of the necessary surveys and repairs, the case will receive the



© 2020

Lloyd's Register  
Foundation

005438

004952 0066

favourable consideration of the Committee with a view to the re-instatement of the class.

I am, Dear Sirs,

Yours faithfully,

Assistant to the Secretary.

Messrs. Empresa Naviera de Cuba Societa Anonima,

(P.O.Box 1641)

6, San Pedro,

HAVANA,

Cuba.

*Copy to HVA*



© 2020

Lloyd's Register  
Foundation

008938 008938 20066