

COPY.

Lloyd's Register of Shipping,



Port of L A G O S.

17th February, 1949.

This is to certify that I have

Surveyed the S.S. TEMARA of London 1033 tons gross whilst the vessel lay afloat and on the dry dock at Lagos on account of a Condition Survey, the Annual Freeboard Survey and repairs,

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and that I have Recommended that she be retained as at present classed with fresh record of survey 1.49; subject to all cargo tanks being scaled internally, specially examined and defective structure dealt with at the next dry-docking and as previously recommended.

being fit to carry Petroleum in bulk.

John Howarth,

Surveyor to Lloyd's Register

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert. B) 1M/2/46 REMPRESS, C.T. 18895

008993.009003.0363