

1m, 5.27.

9 JAN 1928

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Stl. Sc. "SUNFLOWER".

Rpt. Nwc.

No. 82211.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Also see Book

The class is subject to 2 indented shell plates and one frame on starboard bow being faired at the Owners' convenience.

The Newcastle Surveyors now report that some minor alterations have been carried out and the bilges in the boiler room cleaned and examined while the boiler was removed for repairs.

It is submitted the vessel appears worthy to remain as classed, without record of survey, subject as above, as recommended.

as now, subject etc



© 2020

Lloyd's Register
Foundation

3. 1. 28.

008993-009003-0374