

2m,0,49.

5 E

28 MAY 1950

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME RA100. REPORT Hul. No. 56463.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

~~DAMAGE &~~ WEAR AND TEAR.

Some welding repairs in one combustion chamber carried out and other minor repairs to tubes effected.

It is submitted the vessel is eligible to remain as classed without record of Survey as recommended.



© 2021

Lloyd's Register
Foundation

J.H.
8.5.50.

009021-00929-0117