

1

19 NOV 1941

Chief Surveyors.....

Received from Chief Surveyors.....

L'S NAME FLORIDA MARU REPORT Lon No. 109136A

## For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

of Survey ..... When due .....

The Donkey Boiler Survey became due 5.41.

No. 6 crank shaft journal requires to be examined.

In reply to enquiry the KOBE Surveyors write the Owners state they do not desire to continue the classification of this vessel with this Society.

It is added an official letter in confirmation will be forwarded in due course.

It is accordingly submitted the particulars of this vessel be withdrawn from the Register Book and three dots (...) be inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw class  
Insert (...)



*Y. Hall*  
2020  
13.11.41

Lloyd's Register  
Foundation

009040-009049-0225