

14 MAY 1937

s.s. "HOLLAND"

A letter has been received from the Owners stating that this vessel lost her starboard bower anchor in February last while trading in a coastal service in Portuguese East Africa. They purchased another anchor and shipped it to East Africa, but as this anchor was tested by the Bureau Veritas they enclose the certificate and ask that this Society will countersign it.

The weight of the anchor, as shown on the certificate, is suitable for this ship, and the proof test carried out by the Bureau Veritas conforms to this Society's test requirements.

It is submitted that, in the circumstances, this anchor might be accepted for use in this vessel, and the Owners be informed accordingly. The test certificate should be returned to them, and they should also be informed that it is contrary to the practice of this Society to countersign a test certificate issued by another Society.



14.5.37

FRI 14 MAY 1937

Approved
RB

Write on
ret. cert.

~~Write Ret (cfe)~~



© 2021

Lloyd's Register
Foundation

009067-009073-0115