

COPY OF AIR LETTER.

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

71, Fenchurch Street, E.C.3

24th October, 1950.

Classn.
RAJ

Dear Sirs,

I am in receipt of your letter of the 17th instant with its enclosure respecting the Steamer "HOLLAND", the contents of which are noted.

With regard thereto I have to say that it is considered the tube plate flanges should be cropped and part renewed where cracked, in addition to the renewal of the combustion chambers, as recommended.

Yours faithfully,

Clerk to the Classification
Committee.

The Surveyors,
DURBAN.



© 2021

Lloyd's Register
Foundation

009067-009073-0129