

SHIP'S NAME "BETEIGEUSE" REPORT Gen. No. 25816
GB

Outstanding Conditions of Class:

SUBJECT to shell plates G.6 & 7 and H.7 (s.s. from aft) and G.6 and H.5 & 6 (p.s. from aft) being specially examined and dealt with as necessary next drydocking and to the tonnage well (fire damage) being examined and dealt with as necessary on ship's arrival at Genoa.

S.R.L. Appendix. (~~As before~~ None)

Nature of Present Survey: (Afloat ~~and in dry dock~~)

Repairs on account of fire damage, condition of class.

Recommendation:

SUBJECT to shell plates G.6 & 7 and H.7 (s.s. from aft) and G.6 and H.5 & 6 (p.s. from aft) being specially examined and dealt with as necessary next drydocking but without other condition.

As Now. Subject
Without.



1001.
© 2020
2.3.6

Lloyd's Register
Foundation

004235-004242-0124