

s.s. "BOMBARDIER".


--

'Phoned Messrs. Robinson, Brown & Co. and advised them that if this vessel sailed to Italy as a British ship it would be necessary for the vessel to be surveyed with a view to the assignment of Convention freeboards, and this could be done by the Society's Surveyors at Newcastle.

On the other hand if the vessel sailed as an Italian ship it would be necessary for an Italian Convention certificate to be obtained. They should forward a request to the Italian Authorities that this Society be instructed to survey the vessel on their behalf and if necessary to issue a provisional certificate for the voyage to Italy.

The receiver of the message stated that he would inform the party dealing with this case. He stated, however, that the sale has not yet been completed and it is not known what flag the vessel will sail under.

They will advise this Office in due course and no further action need be taken meantime.


11.12.33



© 2020

Lloyd's Register
Foundation

009256 - 009266 - 0243