


S.S. "PORSANGER"

Montreal Nov. 15 22

The screw shaft of this vessel is fitted with a liner the joints of which are stopped.

The New York Surveyors have accepted this method of fitting the liner subject to the screw shaft being specially examined every two years as has been approved by the Committee in several similar cases.

A.R.K.



© 2021

Lloyd's Register
Foundation

009341-009349-0316