

1

SEP 1928

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *M.S. Tendaba.*Report *Don.* No. *90412A.*

## For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement" — Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey

*B.S.*

When due

*6.8.*

The Boiler Survey of this vessel became due at the end of June last. No part of the Survey has been held.

In reply to enquiring the Owners state that the vessel is no longer classed with the Society.

It is submitted the vessel's Class be withdrawn from the Register Book & three dots inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw class  
Insert ...

*C.W.S.*  
*25.9.26.*  
*7/9/26.*  
*M.L.*

© 2021

Lloyd's Register

Foundation  
00435-001360-0043