

et to Chief Surveyors.

Received from Chief Surveyors

VESSEL'S NAME ST. SC. "GARRYOWEN II".

Report London No. 91132A

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/93.)

ature of Survey

Boiler Survey

When due

1. 27.

*The class is subject to repairs being effected to the
& Blm plating at the Owners convenience.*


The Boiler Survey became due at the end of last month.

In reply to enquiry the Owners state that as the vessel seldom leaves Limerick Docks, where she is used as a grain elevator, they do not propose to continue the classification.

It is submitted the vessel's class be withdrawn from the Register Book and three dots inserted in lieu, indicating withdrawal of class at Owner's request.

Withdraw class.

Insert ...



© 2021
2.3.27.

Lloyd's Register
Foundation

009362-009375-0112

Director.