

TELEGRAMS: LLOYDS, DAKAR.

R. P. H. DAVIES
G. C. ANDERSON,
LLOYD'S AGENT.

CODES:
A. B. C. 5TH & 6TH EDITIONS.
BENTLEY'S, WATKIN'S.
SCOTT'S 10TH EDITION.
WESTERN UNION 5-LETTER EDITION.
LIEBER'S.

LLOYD'S REGISTER
Recd. 24 NOV. 1925
LONDON
DAKAR,
SENEGAL.

10th November 1925.


The Secretary
Lloyd's Register of Shipping
71, Fenchurch Street
London E.C.3

Dear Sir,

I thank you for your letter of 14th ult.
enclosing copy of a letter dated 25th January 1924, to
Mr. Anderson with reference to a special Survey to be
carried out on behalf of your Society on the steamer
"COMBO".

I note from a report dated 29th September 1925 ,
received from your Surveyors at Bordeaux, it would
appear that 9 plates in the vicinity of the stem have
been renewed and also that a shoe plate has been fitted
at the after end, where the keel plates were found
chafed.

We regret to note that these repairs were found
to be necessary , not on account of damage received
subsequent to the special Survey No 5 carried out by



© 2021
Lloyd's Register
Foundation

009428-009439-0112 1/2

Referred to the ~~Chief~~ Ship Surveyor,
and the Chief Engineer Surveyor.

RAM.

24 NOV 1325

Also for Mr. S. A. Hill to note.

W.S. Cmdr



© 2021

Lloyd's Register
Foundation

old on
110, 09
REPA

LLOYD'S AGENCY, DAKAR, SENEGAL.

To the Secretary, Lloyd's Register

Sheet No. 2 Date 10.11.25

M. Thibaud , but on account of wear and tear.

I have given a copy of your letter to M. Thibaud together with a copy abstract from Lloyd's periodical Inspection Rules. and trust that you will have no further cause of complain.

yours faithfully.

Bernieudance
LLOYD'S AGENT.
DAKAR.



© 2021

Lloyd's Register
Foundation

0112 2/2