


Lloyd's Register of Shipping,

28¹, Sankt Annæ Plads,

Copenhagen, K. 4th February, 1938.



communications to be addressed
THE SURVEYORS
Lloyd's Register of Shipping,
Copenhagen, K.

reference

S.

The Secretary,

Lloyd's Register of Shipping,

London.

Dear Sir,

In reply to your letter of the 28th ultimo regarding our First Entry Report No. 10433 on the Machinery of the M/S. "COPIAPO" we beg to inform you that the particulars of the Starting Air Receiver given in the report on the Oil Engine Electric Generator Sets refer to the same receiver as those given for the Emergency Starting Air Receiver in the Report on the Main Engines, and as the latter are correct it appears to our regret that some mistake has been made in the first case as regards the internal diameter and working pressure by Rules.

I am, Dear Sir,

Yours faithfully,



Lloyd's Register
Foundation

009440-009450-0168

Referred to the Chief Engineer Surpoper

Also for Mr. [unclear] notes
5 FEB 1938
[unclear]

I am, Dear Sir,
the internal diameter and working pressure by Rules.
that some mistake has been made in the first case as regards
and as the latter are correct it appears to our regret
stating Mr. Receiver in the report on the main engines,
to the same receiver as those given for the emergency
the report on the Oil Engine Electric Generator sets refer
the dimensions of the starting Mr. Receiver given in
specification of the P/S. "COBLENZ" as per to inform you that
relating our first Mr. Receiver No. 10433 on the
in reply to your letter of the 28th ultimo

Dear Sir,

London.
The Secretary,
Coblenz, Register of Shipping,

Coblenz, K. von Lehnfeldt, 1938.

88, Markt August Platz,
Register of Shipping



Lloyd's Register Foundation

© 2021
5 FEB 1938