

COPY.

Lloyd's Register of Shipping.

71, Fenchurch Street, E.C. 3.

21st January, 1922.

Dear Sir,

S. With reference to Glasgow first entry report No. 41592 on the steamer "MONTCALM", it is concluded that three rows of pillars are fitted and not two as stated, but I shall be glad if you will kindly ascertain from the Surveyors and let me know whether this is the case, and also state what is the length and capacity of the F.W.tanks at the sides of the tunnels.

I am, Dear Sir,

Yours faithfully,

Assistant to the Secretary.

The Secretary,

GLASGOW.



© 2021

Lloyd's Register
Foundation

009522-009526-0116