

1

JUL 1927

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Stl.Sc. "CAPE LEEUWIN". Report Lon. No. 91612a.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey _____

When due _____


This vessel was built in 1925-5.

The Sydney Surveyors now forward a letter from the Owners from which it would appear they do not desire to maintain the classification.

It is submitted the class of the vessel be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at the Owners' request.

Withdraw class

Insert ...





29. 7. 27.



© 2020

Lloyd's Register
Foundation

009557-009569-0251