

D.S. 219

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Stl Ls CAPE LEEUWIN Rpt. Syd No. 8759

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


1st Long.Transverse No. 5063Depth "d" 12.16Framing: Table No. ✓Description Built angle frames as approved.2nd Longitudinal No. 12938Proportions Length = 10.0
Depth =~~Deck~~ Sheerstrake As Approved

Revised Rules

This vessel appears to have been built in accordance with the Revised Rules and the approved plans, and it is submitted she is eligible to be classed ✱ 100 A. I. (Steel) with freeboard," as recommended. The Summer freeboard of 8' - 4½" from centre of disc to top of statutory deck line at - deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

2 dks (Stl - Weather dk w.s.).

Cell D.B 167' 202t, Tank above tunnel 20' 71t, F.P.T. 43t, C.A.P.T. 30t.
F.K. BK 1½", 7B.H, pt cmr, Lloyd's A & CP.
B 90'

Lloyd's Register
Foundation

009557-009569-0255 ½ P.T.O. 28/7/25

It is concluded the thickness of the Belge plating, & the sheerstrake and
strake below in way of the Bridge, are as shown on the approved plans,
and that the height of the outside tank brackets, & the stiffening of the
bottom forward are as approved ^{by} the surveyor should be requested to
state if this is so.

It is also concluded that the intermediate frames have been fitted in
way of the Bridge but the surveyor should be requested to state if
this is so.

8.
28.7.25



© 2020

Lloyd's Register
Foundation

009557-004564-0255 2/2