

7-DEC 1928 DISCLOSED  
SECTION No.

219

Received from Chief Surveyors

Chief Surveyors

EL'S NAME S.S. "MARIAMI".

Report London

No. 93245a

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Date of Survey

When due

The Boiler Survey became due in August last.

In reply to enquiry the Owners stated in October that as the vessel was under survey at Greenock in December 1927 the boiler survey was not due until December.

It was explained to the Owners that the survey held at Greenock did not include an examination of the boiler, that examination having been held in August 1927.

In reply to further enquiry the Owners have informed the Bilbao Surveyors that they understood when they purchased the vessel that the boiler survey was not due until December and they add that as they are obliged to have the vessel inspected by the Spanish Government Authorities it is not in their interest to continue the classification and incur the expense of two surveys.

It is submitted the vessel's class be withdrawn from the Register Book and three dots inserted in lieu indicating withdrawal of class at Owners' request.

Withdraw class.  
Insert ...

5.12.28.



© 2021

Lloyd's Register  
Foundation

009570 - 009579 - 0027