

20 NOV 1928

Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

NAME S.S. "MARIAMI". Report London No. 93245a

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Survey \_\_\_\_\_ When due \_\_\_\_\_

The Boiler Survey became due 8.28 but in reply to the usual notice the Owners stated that, in their opinion, the survey should not be due until 12.28 as the vessel was last examined at Greenock in December 1927.

It was explained to them by letter that as the boiler was last surveyed in 8.27 the next survey became due 8.28, but they now reply stating they wish to discontinue the class on the boiler.

IT IS SUBMITTED that the Bilbao Surveyors be requested to take the earliest convenient opportunity of calling on the Owners, explaining the position and endeavouring to arrange for the necessary survey to be held, and the Owners might be advised accordingly.

*In Rhs: L 21/11/28  
for Mr. Samille to note*

*21. 11. 28*



© 2021

20.11.28.

Lloyd's Register  
Foundation

069570 - 009579 - 0034