

# LLOYD'S REGISTER OF SHIPPING



Port C A R D I F F

10th August, 1960.

**This is to Certify** *that I have*

*part of*  
*Surveyed the Machinery of the* s.s. "BEATRICE" ex "TINTERR ABBEY"  
*of Genoa, 2471 tons gross register, whilst in dry dock and*  
*afloat at Barry for Docking, TS., MBS. and General Examination*  
*for postponement of special survey*

*and that I will transmit to the Committee of Lloyd's Register of*  
*Shipping, London, a Report stating that all recommendations made by*  
*me in connection therewith have been carried out to my satisfaction; also*

*that I will Recommend that in the case of this Vessel the following*  
*Survey Records be made in the Supplement to the Register Book*

MBS 8-60 and TS-CL 8-60

*and that her Machinery Classification Record be continued in the Book.*

**Parts now examined:**

(C.S. Items only)

NOTE - The survey of the donkey boiler is overdue but it has been deferred on the understanding that the donkey boiler will not be used.

*J.V. Naylor*

(J.V. NAYLOR)


Engineer Surveyor to Lloyd's Register

**KEY TO ABBREVIATIONS**

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



© 2021

Lloyd's Register  
Foundation