

his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by v

MEMORANDU

om: **LOYD'S REGISTER OF SHIPPING**, 71, FENC  
LON

: The Surveyor(s) at **GENOA**


essel's Name **S.S. "DANIELA T"** **11 MAY 196**

QUESTION

Date:— 9t


I shall be glad to learn what arrangements the Owners propose making for the Main Boiler Survey, due at the end of January last, to be carried out.

I would point out that the ship has not been seen in drydock by the Society's Surveyors, since October 1959, and the Owners' intentions regarding this inspection will also be appreciated.



We are in receipt of a letter from the Owner, Paolo Tomei, of Genoa, us that as the Vessel has compulsorily Classed with Registro Italiano, they have decided to withdraw the V. Class with our Society.



© 2021   
FOR THE SURVEYOR.

Lloyd's Register  
Foundation

PC:SS

COPY TO P

Deck Plates

red? If  
ued?

009789-009795-0099

