



LLOYD'S REGISTER OF SHIPPING

Drottninggatan 62,

~~Bryggaregatan 35a~~, Helsingborg

Telegrams : Surveyor, Helsingborg

24th September, 1962.

Telephone Nos. 10594 & 22130

RECEIVED

25 SEP 1962

VISIT

Reference

C.

The Secretary,
LONDON.

Dear Sir,

CLASSING LETTER.

HB945 "TENTO" - Helsingborg report No.3562.
D - "AXELINE BRODIN" - " - No.3565.

With reference to your letter of the 21st instant we beg to inform you that the starting air pipes of both the above vessels were dealt with as required by the Rules.

It was assumed that the starting air pipes were covered by item 34 "Remaining Piping Arrangements" on the old report form 9 and by "Pumping Arrangements" in the interim certificate and that no special statement regarding same was necessary.

We beg to state that the starting air pipes of m.s. "ODER" (Ex. "CECILIA FALKLAND", Helsingborg report No. 3568, also was dealt with in the same manner.

Yours faithfully,

THE SURVEYORS, Helsingborg



© 2021

Lloyd's Register
Foundation

009815-009826-0246

2

R 2/19/62



© 2021

Lloyd's Register
Foundation