

19th August, 1958.

two

STOCKHOLM

11606, 30, 35, 52 - As recommended.

AREN" 11595 As recommended except that a notation of S.S. Skm 5,58 (Dr) has been assigned, and in this connection I would acknowledge receipt of your letter of the 11th instant.

11581 "CECILIA FALKLAND". This ship has to-day been classed *100A1 together with the appropriate notations recommended by you.

I shall be glad if you will state the rise of floor, as this has been omitted from the report, and at the same time confirm that the thickness of the double bottom pipe tunnel side plates are 10.5mm as reported, as no thickness is shown on the plans forwarded.

Confirmation is also desired that the thickness of the double bottom side girder plates are 8.5mm as shown on the "as built" plans and not 10.5mm as reported.

- 2 -

19th August, 1958.

I duly received your letter of the 1st instant, the contents of which have been noted.



© 2021

Lloyd's Register
Foundation

02572/2