

COPY

Ship's name

"FIREBEAM"

Port

HTL

No. 20307.

Last survey date 5/9/62.

Class is subject to

NIL.

(See also Secretary's letter dated 5th February, 1962).

The Surveyor states that a General Examination of the machinery now commenced with a view to allowing the vessel to return into service until February, 1963 also the Main and Donkey Boilers partly examined but the Surveyor states a General Examination not completed as it has been decided to tow the vessel to the Continent for breaking up.

For the information of the Committee.



© 2021

Lloyd's Register
Foundation