


TELEPHONE: No. 141.

10/

Reference



Lloyd's Register of Shipping,

18½, Regent Quay,

Aberdeen, 3rd July, 1945.

Dear Sir,

Replying to your classing letter "S" dated 29th ultimo, with reference to the "Firebeam" Aberdeen Report No.21635. The Midship Deep Tank was satisfactorily tested. The thickness of the Upper Deck stringer plate at the after end of No.1 Hatchway was fitted .82, these plates were ordered by the Burntisland S.B. Co., and are as fitted in sister vessels, Yard Nos. 252/3/7, .82 plates are also fitted in the sister vessel No.788 now building by Messrs. Hall, Russell & Co. Ltd.,


I am, Dear Sir,

Yours faithfully,

T. Richardson FULHAM VI
WILLIAM PEARMAN FULHAM VII

For The Surveyors.

The Secretary,
WOKINGHAM.



1.c.8

DO

5 JUL 1945



© 2021

Lloyd's Register
Foundation