

COPY  
LLOYD'S REGISTER OF SHIPPING

No. C-11766



Port SHIMONOSEKI,

Date 1st December, 1961.

This is to Certify that I have  
Surveyed the S.S. "EMPIRE MERCHANT" 5,647 Tons gross of Hong Kong on  
the 28th November, 1961 & subsequently whilst she lay afloat at Moji,  
on account of repair to Starboard fwd shell plate,

and that I will transmit to the Committee of Lloyd's Register of  
Shipping, London, a Report, stating that all repairs recommended by  
me have been completed to my satisfaction, also that I will  
Recommend that she be to remain as classed without fresh record  
of survey, subject to Starboard side No.2 shell plate in 4th below sheer  
strake to be specially examined and dealt with as necessary at next  
special survey and also to all conditions attached to the ship's class  
being dealt with as precisely recommended.

Y. Hamada

*Surveyor to Lloyd's Register.*

KEY TO ABBREVIATIONS

AS Annual Survey  
BS Biennial Survey  
DS Docking Survey  
NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey  
SS(Dr) Hull Special Survey (Drilling)  
SS(M) Hull Special Survey (Modified)  
SS(P) Hull Special Survey (Progressive)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-  
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."