

Blue

6m.137.

16 JUN 1937

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

"SAN MATTIAS"

Rpt.

Lon

No. 103

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—Extract from Sub-Committee's Report, 24/5/92.)

Limit & renew circulating pump repairs!

~~No surveys are due on this tanker.~~

The Buenos Aires Surveyors write enclosing a letter from the new Owners of this vessel to the effect that they have no interest in retaining the Society's classification.

It is submitted the vessel's class be withdrawn from the Register Book and three dots (...) inserted in lieu thereof indicating withdrawal of class at Owners' request.



© 2021
15.6.37

Lloyd's Register
Foundation

009879-009887-0261