

The class is subject to main engine crankcase being re-examined by 5.58, and to the windlass motor and casing being renewed by the end of 10.57.

4E
28 NOV 1958

by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

NAME ALFRED PLYM REPORT Ply No. 8652

Docking.

SRL. The above items dealt with and the Surveyor recommends deletion from the List.


IT IS SUBMITTED this vessel is eligible to remain as classed without special condition.

JK

27.11.58

✓
S.R.L. - Appendix Note

Metalock refers to main engine crankcase



© 2021

Lloyd's Register
Foundation

009896-009903-0024