

BANFF PARK	F.E.	Rpt.	Mtl.	No.	5744
JASPER PARK	"	"	"	"	5750
<u>PORT CATARAQUI</u>	"	"	"	"	5751
PORT CONCORD	"	"	"	"	5758

It is submitted the following enquiry be  
 cabled to the MONTREAL Surveyors:-

BANFF PARK, JASPER PARK, PORT CATARAQUI,  
 PORT CONCORD, CANNOT RECONCILE STATEMENTS  
 YOUR REPORTS REGARDING CONNECTION SHELL  
 BUTTS CABLE WHETHER RIVETTED OR WELDED

009896-009903-0231

.....  
 4.1.45

© 2021  
 Lloyd's Register  
 Foundation