

COPY.

# LLOYD'S REGISTER OF SHIPPING



RPT. No. 33722.

Port Buenos Aires

Date 2nd. April, 1962.

**This is to Certify** *that I have*

*Surveyed the* S.S. "MEDINA PRITCHES", 7069 tons gross of Leith  
on the 6th March 1962 - a/e examination of rudder stock cover  
plate and suspected After Peak Tank leakage - Vessel afloat at  
port of Rosario.

*and that I will transmit to the Committee of Lloyd's Register of*  
*Shipping, London, a Report, stating that all repairs recommended by*  
*me have been completed to my satisfaction, also that I will*  
**Recommend** *that she be* retained as now Classed without fresh  
record of survey, subject to After Peak Tank being tested at  
earliest opportunity, and before end June 1962 (3 months) and  
to all other outstanding conditions of Class being dealt with  
as previously recommended.

A. J. Sinclair

C. G. Sinclair

*Surveyor to Lloyd's Register.*


*for H. Gittins (Acting Surveyor to Lloyd's*  
**KEY TO ABBREVIATIONS** *Registrar of Shipping)*

AS	Annual Survey	SS	Hull Special Survey
BIS	Biennial Survey	SS(Dr)	Hull Special Survey (Drilling)
DS	Docking Survey	SS(M)	Hull Special Survey (Modified)
NS	Cargo Battens not fitted (No Sparring)	SS(P)	Hull Special Survey (Progressive)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B)



009896-001903-0328