

COPY  
LLOYD'S REGISTER OF SHIPPING  
UNITED WITH THE BRITISH CORPORATION REGISTER

71, Fenchurch Street, London, E.C.3

Telephone: ROYal 3561 (6 Lines)

Telegrams: Committee, Fen, London

11th February, 1953.

Dear Sirs,

Classn(S)  
RJ3

Your report No. 19796 on the Steamer "BENVANNOCH" received the consideration of the Committee at their Meeting yesterday, and I have to confirm the intimation given to Mr. Dickerson in the afternoon, that your recommendation that repairs to the broken stern-frame should be dealt with as an endorsement of class "B", is not concurred in.

It is considered that this repair should come under the terms of Circular No. 1707A, and accordingly the class has been continued subject to the repairs to the stern frame sole-piece (E.W. and reinforced 12,52) being specially examined at the next drydocking.

Yours faithfully,

Clerk to the  
Classification Committee.

The Surveyors,  
MIDDLESBROUGH.



© 2021

Lloyd's Register  
Foundation

009896-009903-0331