

"BENVANNOCH".

Report No. 3664 dated 23.10.52)

Now done:-

Steering engine examined in its entirety after opening up and found in order.

On completion of repairs to stern post sole piece the steering gear was tried under normal working conditions and found satisfactory.



© 2021

Lloyd's Register
Foundation