



United with
THE
BRITISH
CORPORATION
REGISTER.

Please attach.

Lloyd's Register of Shipping,

95, Bothwell Street, GLASGOW, C.2.

RECEIVED

- 9/JAN 1952

8th January, 1952.

Dear Sir,

And.....

With reference to Dundee First Entry Report No. 9825 on the steamer "EDDYBEACH", I have to state that the weight of the stock of the stream anchor is below the minimum required by the Rules. The Surveyor has stated, however, in reply to enquiry, that the anchors for this ship were supplied by the Admiralty, and it is a matter for consideration, therefore, whether in the circumstances the stream anchor could be accepted.

Yours faithfully,

Whitlock

Secretary to the
Scottish Committee.

The Secretary,
LONDON.



Lloyd's Register
Foundation

CLASSIFICATION

H
C

Handwritten initials and signature:
RC
Erica



© 2021

Lloyd's Register
Foundation

Faint, mirrored text from the reverse side of the page, appearing as bleed-through.