

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report... 10... When handed in at Local Office... 10... Port of London

No. in Reg. Book. 25398 Survey held at on the Wood, Iron or Steel Tug Sc 3 Mast ENUKIDZE Date, First Survey 1923 Last Survey 19

TONNAGE:— GROSS 3908 Built at Haverston Hill on Tees by whom Furness S.B. Co. Ld. When 1923 MONTH 11

UNDER DEK. 33M Owners Savtarglat. Owners' Address (if not already recorded in Appendix to Register Book). Port belonging to Odessa.

Surveyed Afloat or in Dry Dock? ✓ Name of Dock LIS Destined Voyage Oil engine.

B=CellDBorDBa feet; uE&B feet; f feet } Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

Capacity tons. FPT tons; APT tons; MT feet tons. } CHARACTER. Date of last Survey and of Periodical Surveys. Year Assigned and of Survey. Machinery and Boiler Surveys (including date of N.B., if any).

st Report, No. 2248 Port LIS

Medical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the use of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the placement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Special cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined. Society's Freeboard (if assigned) as painted on Ship and now verified } DISCLOSED ins.

Was a damage report made by anyone else? If so, by whom? SECTION No. 672

REPAIRS, OR EXAMINATION AS PER RULE, FOR

PRIMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

ESSENT CONDITION OF THE	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	State if Tanks now tested	Dblng. Plates under Sounding Pipes	(State if on Bolt). When put on, Month Year
Stowings	Bulkheads	Engins Room Skylights	Boats
Rigings & Fastenings	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Outside Plating	Cement or Asphalt (State which.)	Oil Bunkers	Condition, how ascertained (State if wedges removed)
" " in way of sidelights	Rudder	Scuppers	Sails
Stowhooks	Steering gear and its connections	Cargo Hatchways	Equipment letter
Transoms	Windlass	Hatches	Anchors, No. of
Transverse Frames	Have Pumps now been examined and found efficient?	Planking of Wood Vessels	Cables (State if now ranged)
Longitudinals	Have Sluice Valves now been examined and found efficient?	Caulking ditto	" length (on board) mean diamr.
Transverses	Have Watertight Doors now been examined and found efficient?	Treenails ditto	" Rule length size
Floors	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson ditto	Hawser & Warps
Keelsons		Transoms, Pointers, & Crutches ditto	Standing and Running Rigging
Stringers		Timbers of Frame at openings ditto	
Inner Bottom Plating		Ditto Ditto at other places ditto	
		Stringers, Clamps & Shelves ditto	
		Salting ditto (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and pEND24, &c."

Survey Fee (per Section 20)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 20)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me.
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute TUE. 6 FEB 1934 Character Assigned Red Line Surveyor to Lloyd's Register of Shipping. General Committee Thursday, 8th February, 1934. Decision of Classing Committee confirmed.

009924 - 009933 - 0151

If Certificate required? If so, to be sent to