

Lloyd's Register of Shipping,

ENCLOSURES

Via Mazzini No. 9,

Trieste (III), 2nd March 1933.

Casella postale No. 2.



Dear Sir,

S.S. "CARIGNANO".

We beg to inform you that the above vessel has now been assigned new freeboards by the Registro Italiano under the new regulations.

The new marks have been verified as per attached form and the original certificates are returned herewith for cancellation.

The alterations etc. to the vessel consequent upon the re-assignment are as follows:-

ForecWell. DeLife lines for crew fitted.

Bridge Deck. 2 side bunker hatch coamings (1 p., 1 s.,) and 2 hatch coamings to refrigerated store (1 p., 1 s.) removed and openings in deck plated over.-

2 side bunker hatch coamings riveted as necessary.

Handles of doors to machinery spaces made workable from both sides.

After Well. Doors to bridge space renewed in 2 $\frac{3}{4}$ " teak.

Poop. Canvas covers supplied for small skylights.

Companionways strengthened, door sills raised to 18" and doors renewed in 2 $\frac{1}{2}$ " teak.

Poor (cont) Wateright hatch overhauled and put in good order.

General. Hatchcovers and ventilator coaming plugs and covers overhauled.

2 lead scuppers renewed in iron, in No 5 tween deck.

Ventilator coamings and double bottom tank air pipes modified to Convention requirements.

I am, Dear Sir,

Yours faithfully,

A. Hunter

For the Surveyors.

The Secretary,
LONDON.



© 2021

Lloyd's Register
Foundation

Handwritten: (Please send to the Chief Clerk's Office)

Referred to the Chief Ship Surveyor.
(Freeboard).

6 MAR 1933

hull

LONDON.

The Secretary,

For the Zuluwale.

James

Yours faithfully,

I am, Dear Sir,

in connection requirements.

ventilator coverings and double bottom tank air pipes modified
5 test certificates renewed in iron, in No. 2 tween deck.

delivered.
General
Food order.
Boat (cont)

hatch covers and ventilator covering rings and covers

water-tight patch overlaid and put in

