

23 JAN 1958

Received from Chief Ship Surveyor.....

NAME "CANADIAN OBSERVER" REPORT Mtl. No. 11981.

ing Conditions of Class: Subject to sternframe solepiece (E.W. & reinforced 1,54) being specially examined next drydocking.

ment of Certificate (As before ~~or None~~)

due:

SPECIAL SURVEY (B) due 9,57, commenced Mtl. 5,57. See Mtl. letter 17.1.58.

f Present Survey: (Afloat ~~and in dry dock~~)

Examination on account of contact damage.

Features:

in Certificate in order (~~Yes-No-None~~)

tstanding: (~~None~~ for S.S.)

See Mtl.Rpt.No.11617.

be completed by:

ation:

SUBJECT as above, with Endorsement of Certificate, NOTATION of "SS. Mtl. 5,57" being WITHHELD pending completion of the Special Survey.

SUBJECT.

ENDORSEMENT OF CERTIFICATE.

Indents in shell plating (p & s).

~~2 lower anchors and stream anchor on lower (S.S. 12/1/57) to be raised yearly.~~

J. M. W.
26/1/58.

S.S. PART HELD.

It appears from Montreal report No.11617 that the requirements of a General Examination have been complied with.



© 2021

Lloyd's Register Foundation

009462-009425-0065