

9 - MAR 1934

to Chief Surveyors

Received from Chief Surveyors

Steel Sc. "EARL SIGURD"

Report Lon

99763a
No.

VESSEL'S NAME

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

ature of Survey

When due

The Screwshaft Survey became due in 1,34.

The Owners now write to the effect that the vessel is now under Board of Trade classification and should be withdrawn from this Society's class.

It is submitted the class of this vessel be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at the Owners' request.

Withdraw class
Insert ...

[Handwritten signatures]
8.3.34



© 2021

Lloyd's Register
Foundation

009986-009993-0050