

"FORT TADOUSSAC"

Mtl. Rpt. No. 5644.

Mr. Bennett should be advised by
Air Mail that wherever possible in sister vessels, the
3/16" face plates on the 12" channel frames forward of the
half length amidships, should be of greater thickness and
reduced width and not less sectional area.

D^r Montgomery concurs

[Signature]
4.8.42.

*6" x $\frac{9}{16}$ " face plates fitted on 12" channel frames fwd $\frac{1}{2}$ L amidships.
See letter N. Y. 25.8.42*

© 2021

Lloyd's Register
Foundation

009994-010003-0215