

22 JUN 1946

Form C11 (d).

Lloyd's Register of Shipping.

INTERNATIONAL CONVENTION 1930 RESPECTING LOAD LINES.

RENEWAL SURVEY IN ACCORDANCE WITH ART 14 OF THE CONVENTION.

(Port)

Bilbao

(Date)

I have to report that I have surveyed the

*Steamer**Miraflores*

of

Bilbao

on this date.

I have compared the arrangements on board the ship with those given in the original freeboard report and I have found them to be in agreement therewith or equivalent thereto, and the whole to be in efficient condition.

Particulars of repairs or renewals:—

*Trimming plate at aft end of Hatch No. 2 renewed
Hatch web in addition to Hatch renewed
Top and bottom angles in two webs renewed
Hatch web rest angles on the four hatches repaired and made good.
Hatch Covers renewed.*

Particulars of Record and Notation

Recommended for the Special Survey:—

S.S. Bl.º 4.46. (Dr.)

The freeboard marking has been verified and found to agree with the freeboards given on certificate No. _____ dated _____ which is returned herewith. *is stated to have been lost.*

Joe Peraza
Surveyor to Lloyd's Register.

*Is fee paid will be charged
on S. Survey Report*

010056-010066-0050