

Ship's name **AKAMAS**

Port **CEBU**

No. **LA 28**

Class is subject to

Last survey date

**27-5 64**

- (1) M.E. BEDPLATE (METALWORK 1-63) BEING RE-EXAMINED BY 11-64
- (2) PROPELLER, UNDERWEAR FASTENINGS & SEA VALVES BEING SPECIALLY EXAMINED AT NEXT DRY DOCKING
- (3) PLUGGED STAY & PLAIN TUBES & AIR HEATER TUBES IN PORT & CANTER BOILERS TO BE REMOVED AT EARLIEST OPP BY 9-64
- (4) PLUGGED AIR HEATER TUBES & WASTED COMB<sup>n</sup> CHAMBER STAYS TO BE DEALT WITH AT FIRST OPPORTUNITY

*Start.  
Boiler*

T.S DUE 6 64 NOT HELD

MBS DUE 9.63 COMPLETED 11-63 ADVANCED 5-64 & RECORD WITH HELD PENDING SUBJECT ITEMS (3) & (4) BEING DEALT WITH.

SURVEYOR REPORTS STABBY BOILER EXAMINED FOR CONDITION WITH A VIEW TO CONTINUING IN SERVICE. BOILER EXAMINED INTERNALLY & EXTERNALLY WITH MOUNTINGS GENERALLY, ALSO HYDRAULIC TESTING TO 240 LBS/SQ INCH WEEPING TUBES EXPOSED & CONSIDERABLY SATISFACTORY (SUBJECT ITEM (4) ABOVE NOT DEALT WITH)

IT IS SUBMITTED THAT THIS VESSEL IS ELIGIBLE TO REMAIN IN CLASS, SUBJECT AS ABOVE. THE RECORD OF MBS 11-63 BEING WITH HELD PENDING SUBJECT ITEMS (3) & (4) ABOVE BEING DEALT WITH

SEE ALSO REMARKS AT PRR ENDORSEMENT 3) 6/64.

*Cancel.  
see 23/6/64  
v.g.*

Lloyd's Register  
Foundation

*15/6/64*