

LD.

telephone

tral

dford

dee

nburgh

tral

is

al

tral

rcastip

Buryan

field

lston

ood, D

Be

SHE

Tel

charged.

for.

nches.

C.2.

1222

27.8.43.

NLT

LLOYDS REGISTER

MONTREAL

QUEBEC REPORT 5893 CABLE IF THICKNESS STRAKE BELOW
SHEER IN WELLS WITHIN MIDSHIPS HALF LENGTH POINT FIVE
FIVE INCHES ^{also} ~~STOP~~ IF BOTTOM IN TANK UNDER BOILERS
COATED WITH CEMENT OR APPROVED COMPOSITION STOP
STOCKLESS STREAM ANCHOR SHOULD BE FIFTEEN CWT

LLOYDS REGISTER



© 2021

Lloyd's Register
Foundation

010236-010245-0178