

BY AIRMAIL

2

14th January, 1955.

HONG

51, 80, 81, 86, 88, 89, 90, 91, 300 As recommended.

C. 12295 As recommended.

12292 As recommended. In view of the fact that a record of 12,54 has been recommended it is concluded that the steam pipes have been tested in accordance with the Rules, but I shall be glad to give your confirmation on this point as no information in regard to this matter is contained in the report.

Classification Certificates in respect of the Special Survey of the hull and machinery are enclosed for transmission to the Owners if the above matter is in order.



© 2021

Lloyd's Register
Foundation

010276-010282-0028