

TELEPHONE: 2811 (5 LINES)

TELEX: 58-531 ROPNER, DARLNGTN.

TELEGRAMS: ROPNER DARLINGTON TELEX

R. ROPNER & CO. (MANAGEMENT) LTD.

DIRECTORS:

COLONEL SIR LEONARD ROPNER, Bt., M.C., T.D., D.L., M.P.
SIR W. GUY ROPNER. J. R. ROPNER.
R. D. ROPNER. W. G. D. ROPNER.
J. V. ROPNER.
WM. WILEY. CHAS. RINGWOOD

REF. OUR WGE/FW
YOUR

P. O. BOX, No. 18,

CONISCLIFFE ROAD.

DARLINGTON.

ALSO AT LONDON

22nd July, 1959.

For attention of Mr. Cook.

Lloyd's Register of Shipping,
71, Fenchurch Street,
LONDON, E.C.3.

Dear Sirs,

S.S. "OAKBY"

We thank you for undertaking to instruct your Ipswich Surveyor to visit "OAKBY", laid up in the River Stour near Harwich, as soon as he conveniently can and carry out such an inspection as will enable him to issue a Certificate that she is fit to be towed to a near Continental port as an un-Classed ship. We hope Mr. Potts will find no difficulty in issuing the Certificate we require.

Yours faithfully,
SIR R. ROPNER & CO. (Management) LTD.

S. R. Ropner

DIRECTOR.



© 2021

Lloyd's Register
Foundation

010283-010288-0146

APR. 10. 1958

LONDON
Received by me,

Survey Fee (per Section 23)	£ 20	:	0	:	0	:	0
Special Damage or Repair Fee (if any) (per Section 23)	£ 21	:	0	:	0	:	0
Travelling Expenses (if chargeable)	£ 4	:	0	:	0	:	0

CLASSIFICATION

4
mm

DAWINGTON
COMPOSITE BOARD
P.O. BOX 100 10



© 2021

Lloyd's Register
Foundation