

Superintendent - Not required

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE FOR REPAIRS (Wear and Tear and Damage)

Repairs Wear & Tear:-

the line of the after end

Received from Chief Ship Surveyor

19 MAY 1958

SHIP NAME

"OAKBY"

REPORT

Nag.

No. 856

welded

recess

his weld

Existing Conditions of Class: NONE.

Endorsement of Certificate (As before ~~or None~~)

Condition of Present Survey: (Afloat and in dry dock)

Wear and tear repairs.

Recommendation:

As now classed with endorsement of certificate.

As now.

ENDORSEMENT OF CERTIFICATE.

Bottom front plating (p.s.) and shell plating indented.

L.O.E.

Bottom stiffened and Nos. 2, 3 & 4 D.B. tank tops).

Fractured shell plating.



010283-010288-0156

Items:-

or Y.M.
State if on Plate
fitted, Month

Yards, &c.
Condition, how ascertained
(State if wedges)

Endorsement letter
Nos. of
(State if now re-

length
(on board.)

Rule length
Lockers
Mast and Warps

Steering and Running

Eligible in the Register
remain as classed

This ship, so far as now surveyed is eligible in my opinion to remain as classed with

fresh record of survey subject to all other conditions at present attached to the ship

no less being dealt with as previously recommended