

S.F. No 506

SIDE FRAMING

Frame
Numbers.Approved
Scantling
(as Profile)Proposed
Scantling.9-48
57-67
76-115
 $8\frac{1}{2} \times 3\frac{1}{2} \times 54 \text{ fr. } \left. \begin{array}{l} 14" \\ 9 \times 3\frac{1}{2} \times 54 \text{ Rev} \end{array} \right\} \text{ Girder}$
 $9 \times 3\frac{1}{2} \times 48 \text{ fr. } \left. \begin{array}{l} 14\frac{1}{2}" \\ 9 \times 3\frac{1}{2} \times 52 \text{ Rev} \end{array} \right\} \text{ Girder}$

116-142

 $8\frac{1}{2} \times 3\frac{1}{2} \times 50 \text{ fr. } \left. \begin{array}{l} 14" \\ 9 \times 3\frac{1}{2} \times 50 \text{ Rev} \end{array} \right\} \text{ Girder}$
 $9 \times 3\frac{1}{2} \times 44 \text{ fr. } \left. \begin{array}{l} 14\frac{1}{2}" \\ 9 \times 3\frac{1}{2} \times 48 \text{ Rev} \end{array} \right\} \text{ Girder}$

68-76

 $8\frac{1}{2} \times 3\frac{1}{2} \times 60 \text{ fr. } \left. \begin{array}{l} 14" \\ 9 \times 3\frac{1}{2} \times 60 \text{ Rev} \end{array} \right\} \text{ Girder}$
 $9 \times 3\frac{1}{2} \times 54 \text{ fr. } \left. \begin{array}{l} 14\frac{1}{2}" \\ 9 \times 3\frac{1}{2} \times 58 \text{ Rev} \end{array} \right\} \text{ Girder}$

010362-010368-0148

8.10.28

(Derlock) (5060)



Longitudinal Sec

© 2021

Lloyd's Register
Foundation