

COPY

LLOYD'S REGISTER OF SHIPPING



JWK.

Part of ROTTERDAM.

28th March, 1960.

BELONGS TO

ROTTERDAM REPORT

49150

This is to Certify that I have

Surveyed the Machinery of the S.S. "ATHENS", 7161 tons gross of

Piraeus, whilst lying afloat and placed in drydock at this port on

the 4th March, 1960 and subsequently for Condition and Repairs . . .

and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by

me in connection therewith have been carried out to my satisfaction; also

that I will Recommend that in the case of this Vessel the following

Survey Records be made in the Supplement to the Register Book

and that her Machinery Classification Record be continued in the Book, subject to main circulating pump being specially examined and dealt with as found necessary before the end of March, 1961 (1 year limit) and without the condition of class relating to the governors of the generators.

Parts now examined:

(C.S. Items only)

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
CS Continuous Survey of Engines
DBS Donkey Boiler Survey
ES Engine Special Survey
MBS Main Boiler Survey
MES Modified Survey of Oil Engines
OF Fitted for oil fuel (date) FP above 150°F.

SGS Steam Generator Survey
SPS Steampipe Survey
TS Tailshaft Survey
TS(CL) Tailshaft Survey—Continuous Liner
TSN Tailshaft renewed
TS(OG) Tailshaft Survey—Oil Gland

Engineer Surveyor to Lloyd's Register.

D. Kampman.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

„While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, the Surveyors, or other Officers or Agents of the Society.”

ert. B.1.)

010378-010390-0008