

Class is subject to the salt water circulating pump casing being re-examined and dealt with as considered necessary, and the governors of No. 3 dynamo engine being re-tested, all before the end of April, 1960 (6 months limit).

2 MAY 1960

Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

SHIP'S NAME.....ATHENS.....REPORT.....Rot.....No. 49150..

S.R.L.

The above items dealt with, and the Surveyor recommends that the item relative to the governors gear of the generators be deleted from the list and that the main circulating pump be again specially examined and dealt with as necessary before the end of March, 1961 (one years limit).

IT IS SUBMITTED this vessel is eligible to remain as classed, subject as now recommended, without other special condition.



29.4.60.
© 2021

Lloyd's Register
Foundation